

Allgemeine Informationen:

- für Windows 32/64 Bit-Systeme
- kompatibel mit Compact 2.0, Compact 2.0s, Start 2.0s, 4You 100/300-Serie
- notwendig nach einem Wallbox-Update auf 2023.21.11282
- kann auch mit 2021.50.8256, 2021.50.9787, 2023.21.11024 verwendet werden (vollständige Rückwärtskompatibilität)
- Sprachunterstützung für DE, EN, IT, NL - einstellbar direkt im Konfigurationstool

Release Notes für das für das MENNEKES Konfigurationstool 2.22

Verbesserungen

- Erweiterte Einstellungsmöglichkeiten zur Unterstützung der TOR-Richtlinie für Österreich

Release Notes für das für das MENNEKES Konfigurationstool 2.2

Verbesserungen

- Unterstützung der 4You Wallboxen mit Shutter-Steckdose
1311201605BK → AMTRON® 4You 110 11 T2S
1313201605BK → AMTRON® 4You 310 11 T2S
- HMI-Update-Fix
(Überprüfung auf Dateieindung .crc und Möglichkeit, das HMI-Update durchzuführen, auch wenn die HMI nicht mehr startet)
- Unterstützung des externen Energiezählers Carlo Gavazzi EM511 (1-phasig, direktmessend)

Release Notes für das für das MENNEKES Konfigurationstool 2.1

Verbesserungen

- Anzeige der Messwerte (phasengenaue Spannung, Strom, Leistung) des verbundenen externen Energiezählers zur Kontrolle der Installation (Startseite -> Erweiterte Ansicht)
- Neugliederung der "Startseite" mit erweiterten Diagnosemöglichkeiten
- Neugliederung der Seite "Einstellungen" in logische Abschnitte: Allgemeine Einstellungen, Kompatibilität, Solares Laden, Modbus RTU, Energiezähler, Energiemanager (geräteabhängig)
- Anzeige der Mindestladeleistung in Watt im Solarunterstützten Laden auf Basis der einstellbaren Phasigkeit und des Ladestroms (geräteabhängig)
- Modbus-Adresse der Wallbox im Bereich von 10-50 auswählbar (ab SW 2.0 2023.21.11024 für Geräte in Verbindung mit einem Energiemanager)
- Dateigröße des Störungslogs reduziert

Hinweis: Bestehende Installationen des Konfigurationstool vor der Installation der neuen Version schließen. Bei Problemen wird außerdem empfohlen, bestehende Installationen des Konfigurationstools zu deinstallieren (unins000.exe im bestehenden Installationsordner ausführen) und das Konfigurationstool 2.2 erneut zu installieren.

General information:

- for Windows 32/64 bit systems
- compatible with Compact 2.0, Compact 2.0s, Start 2.0s, 4You 100/300 series
- necessary after a wallbox update to 2023.21.11282
- can also be used with 2021.50.8256, 2021.50.9787, 2023.21.11024 (full backwards compatibility)
- Language support for DE, EN, IT, NL - can be set directly in the configuration tool

Release Notes for the MENNEKES configuration tool 2.22

Improvements

- Extended configuration options to support the TOR policy for Austria

Release Notes for the MENNEKES configuration tool 2.2

Improvements

- Support for 4You wallboxes with shutter socket
1311201605BK → AMTRON® 4You 110 11 T2S
1313201605BK → AMTRON® 4You 310 11 T2S
- HMI update fix (Check for file extension .crc and enable HMI update even if the HMI no longer starts)
- Support for the external energy meter Carlo Gavazzi EM511 (1- phase, direct measuring)

Release Notes for the MENNEKES configuration tool 2.1

Improvements

- Display of the measured values (phase-accurate voltage, current, power) of the connected external energy meter to check the installation (Start page -> Extended view)
- Reorganisation of the start page with more diagnostic options
- Reorganisation of the settings page into logical sections: General settings, Compatibility, Solar charging, Modbus RTU, Energy meter, Energy manager (device-dependent)
- Display of the minimum charging power in watts in solar-supported charging based on the adjustable phase usage and charging current (device-dependent)
- Modbus address of the wallbox can be selected in the range of 10-50 (from SW 2.0 2023.21.11024 for devices in combination with an energy manager)
- File size of the fault log reduced

Note: Existing installations of the configuration tool must be closed before installing the new version. In the event of problems, it is also recommended to uninstall existing installations of the configuration tool (run unins000.exe in the existing installation folder) and reinstall the configuration tool 2.2.